

# COLORCARD

 <b>WASA-001</b> N-Free	 <b>WASA-002</b> Dull N-Free	 <b>WASA-003</b> Zinc	 <b>WASA-004</b> Stainless
 <b>WASA-005</b> Brass	 <b>WASA-006</b> Dull Brass	 <b>WASA-007</b> Gold	 <b>WASA-008</b> Dull Gold
 <b>WASA-009</b> Red Anti-Brass	 <b>WASA-010</b> Anti-Brass	 <b>WASA-011</b> Anti-Brass Light	 <b>WASA-012</b> Dark Anti-Brass
 <b>WASA-013</b> Pewter	 <b>WASA-014</b> Dark Pewter	 <b>WASA-015</b> Dull Dark Pewter	 <b>WASA-016</b> Anti-Copper
 <b>WASA-017</b> Shiny Copper	 <b>WASA-018</b> Red Copper	 <b>WASA-019</b> Dull Copper	 <b>WASA-020</b> Copper Pewter Dull
 <b>WASA-029</b> Black Structure	 <b>WASA-030</b> Shiny Black	 <b>WASA-031</b> Dull Black	 <b>WASA-032</b> Rubber Black

All finishes are nickel free (except the ones marked with \*),  
and in accordance with REACH and Oekotex.

# COLORCARD

	<b>WASA-033</b> Alloy		<b>WASA-034</b> Mildewed Alloy		<b>WASA-035</b> Old Silver		<b>WASA-036</b> Graphite Grey
	<b>WASA-037</b> H-Polish Gold		<b>WASA-038</b> H.Polish Gunmetal		<b>WASA-039</b> H.Polish N-Free		<b>WASA-040*</b> H.Polish Pearl
	<b>WASA-041</b> Brushed Anti-Brass		<b>WASA-042</b> Brushed Copper		<b>WASA-043</b> Brushed Brass		<b>WASA-044</b> Brushed Anti-Silver
	<b>WASA-045</b> Oxidized Brass		<b>WASA-046</b> Oxidized Anti-Brass		<b>WASA-047</b> D.Oxidized Anti-Brass		<b>WASA-048</b> B.Oxidized Copper
	<b>WASA-054</b> Black Copper Red		<b>WASA-055</b> Tin Black		<b>WASA-056</b> Tin Bright Brass		<b>WASA-057</b> Tin Copper
	<b>WASA-058</b> Tin		<b>WASA-059</b> Rusty Metal		<b>WASA-060</b> Red Graphite		<b>WASA-061</b> Dark Alloy
	<b>WASA-062</b> Dim Anti-Copper		<b>WASA-063</b> Old Pseudo Anti-Silver		<b>WASA-064</b> Sand Black		<b>WASA-065</b> Metallic Red

All finishes are nickel free (except the ones marked with \*), and in accordance with REACH and Oeko-tex.